

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF- ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION	
LEAL, ERNESTINE	101 DUNN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
ST STEPHENS LUTHERAN PARSONAGE	102 DUNN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
LEAL, VALENTEN	103 DUNN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
O'BRIEN, ANDY	105 DUNN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
CLAAS, THOMAS M	110 DUNN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
THORSON, RACHEL & KEVIN	441 S MAIN ST	N	C	N			C			SF						Installation record	Y			Field inspection only	Y				
MURPHY, ERIC	242 N MAIN ST	N	C	N			C			SCH/DC						Installation record	Y			Field inspection only	Y				
MESSER, ROBIN	202 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y				
CHASE, ANDREA	210 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y				
CARROLL, DAVID & PATRICIA	218 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y				
TAVS, MIKE	226 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y				
SCHMIDT, DAVID & DEBRA	234 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y				
LOBERGER, JEREMY & MILA	109 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
MCENDREE, LORA	115 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
BUCKINGHAM, MELISSA	121 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
ABEGGLEN, RICHARD	127 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
GRETZINGER, TIM	128 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
BORDE, CARLA	208 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
ABEGGLEN, JOYCE E.	209 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
MILES, BONNIE	214 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
HUFNAGEL, ADAM	215 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
NOVOTNY, TRACY & JESSICA	220 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
ANDERSON, CHRISTOPHER	225 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
MOODIE, TOM & KAREN	228 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
DAMICO, ERIN	235 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
PASEWALD, MICHELE	236 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
HARRIS, ALYSON	237 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
COLOTTI, BODIE	243 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
MORAUSKE, MAYNARD	244 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
POWERS, GARY	253 CHURCH ST	N	C	N			C			SF						Previous eval	Y		Other - describe in notes	Field inspection only	Y			Other - describe in notes	Visual insp during sanitary sewer replacement
MORTON, TRENT	242 SLEEPY HOLLOW RD	N	C	N	3/4"	1974	C			SF						Installation record	Y	1974	Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
SMITH, BRIAN	245 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
SILVA, MARTIN	253 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
MEIERDIRK, SAWYER	261 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
VERMILLION, JAMES	269 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
VEITH, AMBER	277 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
GARCIA, SHANNON & JESUS	285 SLEEPY HOLLOW RD	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
SOTER, JOSHUA	518 SLEEPY HOLLOW RD L	N	C	N	1"		C			SF						Installation record	Y		Visual insp during install or repair	Field inspection only	Y			Visual insp during install or repair	
FALL RIVER SCHOOL	150 BRADLEY ST	N	DI	N			C			SCH/DC						Installation record	Y			Installation record	Y				
FALL RIVER SCHOOL	150 BRADLEY ST	N	DI	N			C			SCH/DC						Installation record	Y			Installation record	Y				
FALL RIVER SCHOOL	150 BRADLEY ST	N	DI	N			C			SCH/DC						Installation record	Y			Installation record	Y				
DIAZ, ABDON & MARIA	106 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
SCHEEL, ROBERT	107 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
FREDENBERG, ROBERT	112 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
BRADLEY, RUSSELL & MELISSA	113 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
MICHAEL, RANDY & CHERYL	118 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
FLETCHER, JAMES & DIVINA	119 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
STOWELL, DAVID & PATRICIA	124 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
MILLARD, DUSTIN & ASHLEY	130 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
UTTECH, MIKE	136 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
FOULKES, PHYLLIS	141 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
BEAL, KENNETH	142 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
HOLMES, JIM & LEJIE	147 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
ST. GERMAIN, BRANDON & PAT ANN	148 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
SCHMITT, DALLAS	153 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
CHALLONER, MARK & KIMBERLY	154 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
ABEGGLEN, CRAIG & JILL	159 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
WENDT, JIM & LAURA	160 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
WESOLOWSKI, BEN	166 CARDINAL LN	N	C	N	1"	2002	C			SF						Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
HIGLEY, ROBERT & MARY	171 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
LANG, PAUL & KIM	177 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
VERDON, DARCI	183 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
LANGE, JUDY	189 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
BIRKETT, DALE & MARCIA	195 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
COENEN, SCOTT	199 CARDINAL LN	N	C	N	1"	2003	C			SF						Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
GILL, DEVIN	301 CHURCH ST	N	C	N	1"	2022	C			MF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
JONES, JENNIFER	303 CHURCH ST	N	C	N	1"	2022	C			MF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
HERNANDEZ, TONY	309 CHURCH ST	N	C	N	1"	2022	C			SF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
NINMANN, JOHN/TARA	501 CHURCH ST	N	C	N	1"	2022	C			SF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
KLEIN, JOHN	509 CHURCH ST	N	C	N	1"	2022	C			SF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
NEWTON, JOHN	511 CHURCH ST	N	C	N	1"	2022	C			SF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
SMITH, BRIAN	515 CHURCH ST	N	C	N	1"	2022	C			SF						SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022		Visual insp during install or repair	
STUEBER, JOSEPH	100 COMMUNITY DR	N	C	N	1"	2006	C			MF						Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y			Visual insp during install or repair	
LATINEN, RONALD & DORTHY	101 COMMUNITY DR	N	C																						

SCHULENBURG, NICOLE	138 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
GUENTHER, ASHLEY	141 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BRUCHMAN, COREY	142 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
MASON, ELIZABETH	143 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
MOUNGEY, DEBORAH	144 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BAYER, BRITTANY	145 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BORRESON, MOLLY	147 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LEISSES, BRAD	148 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
MIJARES, JUAN	149 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
POWLEY, BECKY	150 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
ATENCIO, MAGGLEY	151 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SMITH, JENNIFER	153 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
RIBBLE, ALYXANDREA	155 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
FAIRBANK, RANDY	157 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
NELLER, JORDAN & MICHELLE	159 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
WINTER, GABRIEL	161 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SENNHENN, NEAL	163 COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
PARK EDGE CONDO ASSOC	103A COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
PARK EDGE CONDO ASSOC	111A COMMUNITY DR	N	C	N	1"	2006	C	MF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
FRANKLIN, JOHN	101 DEER RUN	N	C	N	1"	2003	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
FRANKLIN, JOHN	103 DEER RUN	N	C	N	1"	2003	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
YELK, CRYSTAL	111 DEER RUN	N	C	N	1"	2003	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LOGA, TROY & REBECCA	113 DEER RUN	N	C	N	1"	2003	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
ABEGGLEN, DAN & MARGE	150 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
HEUER, RYAN A.	151 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LAITINEN, LINDA	152 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SCHWENN, DAN	153 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
GOERING, JUSTIN	159 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
KELLY, TODD	160 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
PAWLISCH, TOM	165 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
DIETZENBACH, MATT & MEGAN	166 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
WIEMER, BRANDON & ANGELA	171 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
DYKSTRA, BRIAN	172 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SCHLACHTER, MIKE	177 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SCHULTZ, TIM	178 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
EDGE, AARON & REBECCA	184 DEER RUN	N	C	N	1"	2003	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
STEINER, CHASE & HOLLY	102 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
CASE, ADAM	107 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
JONES, CHAD	110 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BEAUDOIN, JAMES & TRACY	111 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
TURK, DAVID	115 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SHEPARD, FUZZY	121 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SCHUETZ, JEFF & KIMBERLY	127 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BROZET, DAVID	133 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
OELKE, ARNIE	136 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
MEISTER, KIM & DEB	140 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LANGE, DALE	141 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
FOX, JAMES	148 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LIEZOW, TRENT & JENNIFER	149 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BAHR, ROBERT & DENISE	156 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
ADAM, GENE/BETSY	157 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
NEUMAN, BRIAN	164 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
CUTSINGER, NICHOLAS & JENNIFER	165 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
OELKE, DAWN & DEXTER	172 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
GONZALEZ, JUAN & KATIE	173 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
LENZ, CLINT	180 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
TALG, DWANE	181 DYKSTRA DR	N	C	N	1"	2000	C	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
SLOAN, CHRIS	188 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
REMUS, MATT	189 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
KUFAHL, DALE	190 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
REYNDERS, RACHAL & JOSEPH	191 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BEAL, MICHAEL	200 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BAUS, REBECCA	202 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
DREHMEL, TAMERA J	204 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
HARDMAN, ROBERT	206 DYKSTRA DR	N	C	N	1"	2000	C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
EK POWER PRODUCTS	465 EK WAY	N	DI	N	6"		DI	NONRES	Installation record	Y		Diameter > 2 inches	Y		Visual insp during install or repair	
JACOB, DAN	201 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
GROSSMAN, DARYL	203 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
BERNDT, WILLIAM	205 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
HOGLUND, MATT & JANET	207 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
SANTOS, NIKO	329 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
KNOWLES, REGINA	331 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
ELLIOTT, TINA	333 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
POLLOW, PAUL & KRYSTAL	335 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
MOLL, CAMARON	337 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
KAMMERUD, DAVID & SARAH	339 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
MILLER, CHRISTOPHER	341 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
METZ, ZAC & DIANA	343 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
MARTIN, AARON	345 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
JONES, RENEE	347 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
POLK, JORDAN	349 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
SLOAN, KEVIN	351 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
PESEK, DANIEL	353 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
ENGEL, MARK & CHRISTINA	355 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
WHITSON, KELLY	357 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
FREDRICKSON, JAY	359 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
JOHLL, KATHRYN	361 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
ALTMAN, AMY	363 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
DELEON, JESSICA	365 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
CHRISTIANSOON, CODY	367 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
LEITZ, GARETT	369 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
KREBS, JOHN	371 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
MATUSZESKE, MICHAEL & TAMMY	373 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
GILL, BILL & JOLENE	375 FOX TRL	N	C	N			C	MF	Installed after lead ban	Y		Installed after lead ban	N			
DIANCIN, CONNIE	101 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
DEACRUZ, CLARO	103 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
DUNNING, CHARLES B	109 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
BEAL, EDWARD	118 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
WATTERS, JUSTIN & CANDY	119 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
MICKELSON, ROBERT	126 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
LARSON, CHEYENNE	134 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair

SCHUMANN, JACK	135 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
SZYMANSKI, BEN	142 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
RANEY, CYNTHIA	143 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
WELCH, CHRIS	150 HILLTOP DR	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
CASTLEBERG, SHAWN	151 HILLTOP DR	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
JUNGENBERG, RONALD	159 HILLTOP DR	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
BREITENFELDT, MIKE	167 HILLTOP DR	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
BAKER, LARRY & MARY	175 HILLTOP DR	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
THE MEADOWS	101 HOMETOWN AVE	N	DI	N			DI	MF	C	Installation record	Y		Installation record	Y	2022	Cross-connection survey
GERICKE, JOHN	208 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
JERANEK, MEGAN	210 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
THOENNES, CINDY	212 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
LOECHER, ANTHONY	214 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
LAWSON, MARJORIE	215 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
MUNSON, NICHOLAS	216 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
YUDS, LINDSEY	217 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SCHMITZ, CINDY	218 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
FATTY, SARA & EBRIMA	219 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SMITH, LARRY & JILL	220 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMMAN, ALYSSA	221 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
VENDEN, MICK	222 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
PETERSON, AMANDA	223 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
NICHOLS, ANNETTE	224 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
LEVERSON, BRADY	225 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
WALTERS, SERENA	226 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SCHMIDT, JEFF	227 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
COTE, JEANNIE	228 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SALTER, SUE	229 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
STINSON, COLIN	230 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
NELSON, SARAH	231 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
PAZYNSKI, STEVEN & TRENA	232 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
PAVLOSKI, NICHOLAS	233 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
VERDIER, QUENTIN	234 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HERWIG, SHELLY	235 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
ACKER, TAMMY	237 HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN ASSOCIATION	212A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN CONDOMINIUM ASSOC.	219A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN CONDO ASSOC.	220A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN CONDOMINIUM ASSOC.	224A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN CONDOMINIUM ASSOC.	229A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOMETOWN CONDOMINIUM ASSOC.	232A HOMETOWN AVE	N	C	N	1"	2006	C	MF		Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SLACK, SCOTT	107 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
PELLETT, BERNARD & JUDY	109 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SMITH, SCOTT	110 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
STROOK, JASON & BRIE	117 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
ONSGAARD, JEFF & BONNIE	118 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
CORNELL, KATHLEEN	125 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
GOLDADE, STEVEN & DARLENE	127 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
TESCH, SARAH	133 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
WOOLLEY, KARI	135 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
VOTH, ABBEY	137 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOESCHELE, JULIE	139 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
REES, TERRI	153 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
AUGUSTINE, JOSEPH	157 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
WELCH, BEVERLY	161 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HOKE, JEREMY	165 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
WENTZ, MARY JO	169 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
JUECH, RUTH	171 JENNIFER LN	N	C	N	1"	1996	C	MF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
MAZZOCCHI, DANIEL & AMY	199 JENNIFER LN	N	C	N	1"	1996	C	SF		Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
DAVIS, JACLYN	202 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
EHLKE, ROGER/JUDY	207 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
EVERSON, DONALD	210 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
OLSON, TERRY & LAURIE	215 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
KALTENBERG, WILLIAM	218 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
STAL, MATHEW	223 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
SCHULTZ, BRYAN & ALYSSA	226 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
DEAKIN, DALE	231 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
NEUMAN, DARREN & TAYLOR	234 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
PERGANDE, JEREMY	239 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
BUKOSKI, SUMMER	247 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
BRENNER, SCOTT	255 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
BAKER, DAVID	263 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
HULL, KRISTIE	271 JENNIFER LN	N	C	N	1"		C	SF		Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair
BEERS, GREG	197 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
TAYLOR, KATHERINE	204 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
MILES, JEFF	207 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
KAMINSKI, AMY	211 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
SCHUCHARDT, JANE	217 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
LUETH, DAVID	223 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
HAUPTLI, SHEENA E	230 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
TAMMINGA, DAKOTA	231 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
NICHOLLS, BRANDON	240 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
HANSEN, VICKIE	300 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
JOHNSRUD, DEREK	309 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
BOOK, KEVIN & KRISTIN	310 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
TRAMBURG, JOLENE	315 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
KRAKOW, RUSSELL	318 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
NEUMAN, ANDREW & WHITNEY	321 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
OSGOOD, MICHELLE	324 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
JOHNSRUD, BRADLEY	327 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
BLEVINS, CHRISTOPHER/KATRINA	330 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
VOSS, TAMMY	335 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
WHITSON, JIM & MARTI	336 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
SMITH, MEGAN	402 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
ADAM, LISA	405 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
PIEKARSKI, MATTHEW	409 KANE ST	N	C	N			C			Installation record	Y		Other - describe in notes	Previous eval	Y	Visual insp during sanitary sewer replacement
PRIEM, EVELYN	410 KANE ST	N	C													

ACE, WILLIAM	426 KANE ST	N	C	N		C		Installation record	Y		Other - describe in notes	Previous eval	Y		Other - describe in notes	Visual insp during sanitary sewer replacement
LANG, BENJAMIN	434 KANE ST	N	C	N		C		Installation record	Y		Other - describe in notes	Previous eval	Y		Other - describe in notes	Visual insp during sanitary sewer replacement
CHAFFEE, RYAN & MELISSA	458 KANE ST	N	C	N		C		Installation record	Y		Other - describe in notes	Previous eval	Y		Other - describe in notes	Visual insp during sanitary sewer replacement
KAUFMAN, JOHN	555 KANE ST	N	C	N		C		Installation record	Y		Other - describe in notes	Previous eval	Y		Other - describe in notes	Visual insp during sanitary sewer replacement
BROWN, MATTHEW & MELISSA	100 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
JAYNES, JEREMY	101 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
HANSEN, RYAN & KAITLIN	103 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
GROSSMAN, MARY	104 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
REED, ROBERT & CONSTANCE	107 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
TAUER, DENNIS & RITA	108 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
CORLETT, AARON & BAILEE	111 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
PATRICK, DALE & DAWN	112 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SWENEY, TODD & JULIE	115 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
WHITTINGTON, WILLIAM	116 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SAMPOLINSKI, SCOTT & JESSICA	119 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
GARNER, JAMES	120 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SAWYER, MARK & LISA	123 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
BOBHOLZ, MARCUS	124 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHMIECHEN, ANDREW	127 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
BIRR, DAN & KIERSTEN	128 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
EGGERT, CINDY	131 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
LOEFFLER, DALE	132 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
WALKER, TERRY	135 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHNEEKLOTH, TYLER & JENNIFER	139 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHLEIF, CHADRON & KELSEY	140 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
PARKER, LEVI & JAIME	143 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
MOEHR, CHRISTOPHER & RACHEL	144 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHUMANN, ERIC	147 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
NEMECEK, DEAN & KRISTIN	148 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
DYKEMA, JOSHUA & DANA	151 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
GARDNER, JOHN	152 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
JENNINGS, DERRICK & HEIDI	155 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
ABEGGLEN, JEREMY & HEIDI	159 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
DYKSTRA, CHAD & COLLEEN	160 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
AMGALAN, ENKHBAYAR	163 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
FELDER, JERRY	167 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
BADER, STEVE	171 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHUMANN, MARK	172 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHROUD, MARTHA	175 LAZY LAKE DR	N	C	N	1"	1998	C	SF		1998	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
ANDERSON, JUDY	190 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHMITT, TYLER	192 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHMUHL, AMANDA	200 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
ANTON, NATHAN	202 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
WAHL, KATHY	204 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
FREEMAN, DEB	206 LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
HOMETOWN CONDOMINIUM ASSOC.	200A LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
HOMETOWN CONDOMINIUM ASSOC.	206A LIENKE RD	N	C	N	1"	2006	C	MF		2006	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
LANDMARK CREDIT UNION	120 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
MARKHARDT, SARAH	150 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
SCHMIDT, JOLENE	154 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
MARKHARDT, SARAH	158 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
MANE ATTRACTION	162 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
LEPKE, KAITLIN	166 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
WINGZ N THINGZ	170 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
NOLDEN PROPERTIES LLC	172 MCCRAE RD	N	C	N	2"	2000	C	NONRES		2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair	
OELTIENBRUNS, KEVIN	130 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
SCHMID, DAVID	203 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
ST STEPHENS LUTHERAN CHURCH	221 N MAIN ST	N	C	N	1"	2003	C	NONRES		2003	Visual insp during install or repair	Field inspection only	Y	2023	Cross-connection survey	
FALL RIVER SCHOOL BUS GARAGE	224 N MAIN ST	N	C	N	1"	2003	C	NONRES		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
RABL, LEANN	304 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
RAYMOND, KEVIN	307 N MAIN ST	N	C	N		2003	C	NONRES		2003	Visual insp during install or repair	Field inspection only	Y	2023	Cross-connection survey	
E-Z AXIS	310 N MAIN ST	N	C	N		2003	C	NONRES		2003	Visual insp during install or repair	Field inspection only	Y	2023	Cross-connection survey	
EHLERS, DONALD	320 N MAIN ST	N	C	N	1"	2003	C	NONRES		2003	Visual insp during install or repair	Field inspection only	Y	2023	Cross-connection survey	
DILLMAN, JACOB & DAWN	321 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
SCHULTZ, ERIC & HEATHER	407 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
GOOD, JONATHAN	412 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
GOESSL, RUSSELL	415 N MAIN ST	N	C	N	1"	2003	C	MF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
BAUMAN, DEBRA	417 N MAIN ST	N	C	N	1"	2003	C	MF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
FRANCIS, CARL	418 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
RIVERA, GIOVANNI RAMOS	421 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
BAUMAN, TINA	424 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
CIANCIO, BRANDON	425 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
FISHER, DARYEL & LINDA	432 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
REIFOWITZ, WOODY & SARA	433 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
PEREZ GALLO, JORGE OMAR	437 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
WODILL, EUGENE	438 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
ERDMANN, JAMES P	445 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
GATES, PAUL	448 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
OBRION, LAURA	452 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
HANLON, HEATHER	455 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
KENNEDY, RONALD	458 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
BUHLER, ROBERT	461 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
NICHOLS, JAMIE	467 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
DRIVER, TATIANA	470 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
WOOD, ANDREW & KATIE	475 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
KRAUSE, GERALD	505 N MAIN ST	N	C	N	1"	2003	C	MF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
SCHMID, DAVID	506 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
SEIBT, LEE	507 N MAIN ST	N	C	N	1"	2003	C	MF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
CAMPTON, CARRIE	509 N MAIN ST	N	C	N	1"	2003	C	MF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
CORNING, BARB	512 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
ROUNDY, BOBBIE	513 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
RANDALL, JOANNE & STEVE	518 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
KOCI, MIKAIL	519 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
LETO, JEFF	525 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	
TOMAN, TODD & LAURA	528 N MAIN ST	N	C	N	1"	2003	C	SF		2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair	

HORNE, JASMIN	604 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SCHOENWETTER, JASON	606 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DONOHUE, CHRISTEEN	608 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WEBSTER, DREW	610 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SPELLMAN, MIKE	612 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SORIANO, ESTHER	614 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GREILING, BRIAN	616 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HURCKMAN, SHANDI	618 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SENNHENN, BRIAN	630 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DYKSTRA, RACHAEL	640 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SUCHOMEL, DANIEL	650 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
CASWELL, AMBER	652 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
RETZLAFF, JASON	654 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VANDEHEY, JEREME	656 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VANDEHEY, JEREME	658 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FOULKES, DIANE	660 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BAIMA, EDDIE	662 N MAIN ST	N	C	N	1"	2003	C	SF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VANDEMERWE, WENDY	664 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
JESSE, MICHAEL	666 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MAAS, JEREMY & BECKY	670 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WB ENTERPRISES	672 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GEIGER, KYLE	674 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
NELSON, ERICA	676 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HOSKINGS, KEVIN & DENISE	678 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
JAYNES, SHAUNA	680 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HANSEN, COURTNEY	682 N MAIN ST	N	C	N	1"	2003	C	MF	SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VG CONDO	700 N MAIN ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
VG CONDO	702 N MAIN ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
GRADINJAN, CECELIA	704 N MAIN ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Field inspection only	Y	2023	Visual insp during install or repair
ABRAHAM, SANDY & KEVIN	706 N MAIN ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Field inspection only	Y	2023	Visual insp during install or repair
SCHULTZ, CODY & CLAIRE	100 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
WERTMAN, KENNETH & SARAH	106 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
ROHRBECK, LINDA	112 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
BIRR, DENNIS & CYNDI	115 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
RILEY, TROY	118 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
AXELSEN, ROBERT & VALERIE	123 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
KRENZ, GREG & BRITTANY	124 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
VEITH, JENNI & DENNIS	125 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
VANDERMOLLEN, CRAIG & CYNDI	130 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
PETERSON, BRIANA	135 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
DOLLAK, MIKE	136 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
JOHNSON, SALLY	141 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
STIEVE, MARC	142 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
FANDRICH, TROY & HOLLY	148 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
TRAUTMAN, LYLE	153 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
OSTRANDER, PENNY	154 NATURES TRL	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
LAKE, JACKIE	95 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
TAYLOR, THERESA	97 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
STOCKS, HALEY	99 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
COOP, JASON	105 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
CORLETT, WENDY	106 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
GEHRKE, BRUCE	117 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
CLARK, DAWN M	118 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SZEPHENEC, LUCAS	129 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
ROBBINS, SAM	130 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
KAUFMAN, JILL	141 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
LLOYD, TRAVIS	142 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
VOSBERG, HEATHER	153 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
EBERT, MICHAEL J	154 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
WHITE, JOHN	165 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
DIAZ, FERNANDO & MARIA	166 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
PEARSON, TWILA	203 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
STRELOW, BRYON	216 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
FISHER, KYLE	218 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
TAYLOR, SHAWNA	226 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
GARRISON, IODI	227 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
MOUNGEY, JOSHUA	228 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
CZARNEZKI, TONYA	238 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
FISCHER, PAUL & THERESA	240 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
PELLETT, DANIEL	243 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
MARTINSON, CHRIS	248 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
ROHRBECK, DAWN	250 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SKILTON, LINDA	251 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
ALLEN, CHRISTINE & KENNETH	259 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
GOULD, MAX	262 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SCHNURR, MATTHEW & KATHRYN	267 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SANFORD, CLARENCE	268 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
RUPPEL, JENNY	274 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
HANSON, KEITH & SHARON	275 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
WOUNDSTRA, JAMES	280 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SULLIVAN, JUDY	283 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
HURST, JEFFREY	286 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
GROSSMAN, KEITH & BEV	291 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
GOULD, MARK	292 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
CHASÉ, BRIAN	298 NIEHOFF DR	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SAVANNA OAKS CULTURAL CENTER	100 POSER RD	N	DI	N	1"		C	NONRES	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
ARNOLD, JESSE	109 PRAIRIE ST	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
KOEHLER, KATHY	114 PRAIRIE ST	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
LARSON, DIANE	175 PRAIRIE ST	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
WAGNER, BILLIE	212 PRAIRIE ST	N	C	N	1"		C	SF	Installed after lead ban	Y		Visual insp during install or repair	Installed after lead ban	N		
SACQUITNE, ANDREW	301 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
MORSCHAUER, PAUL	307 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
FALL RIVER SCHOOL SPORTS COMP	310 PRAIRIE ST	N	C	N	1"	2020	C	SCH/DC	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
SWENO, DUWAYNE	313 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
GREILING, AARON	319 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
LISKA, FRANK & PEGGY	325 PRAIRIE ST	N	C	N	1"	2018	C	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
DAUMAN, JORDAN & HANNAH	331 PRAIRIE ST	N	C													

WIDELL, SPENCER	361 PRAIRIE ST	N	C	N	1"	2018	C	SF		Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
FALL RIVER EXPRESS	143 QUALITY CT	N	DI	N				NONRES		Visual insp during install or repair			Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BADGER EXPRESS	161 QUALITY CT	N	DI	N			C	NONRES		Installation record			Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
BADGER EXPRESS	181 QUALITY CT	N	DI	N			C	NONRES		Installation record			Visual insp during install or repair	Installed after lead ban	Y	Visual insp during install or repair	
METALCRAFT OF MAYVILLE INC	400 QUALITY CT	N	DI	N	6"	2004	DI	NONRES		Installation record	Y	2004	Visual insp during install or repair	Diameter > 2 inches	Y	Visual insp during install or repair	
BADGER CUSTOM PALLET LLC	450 QUALITY CT	N	DI	N	6"	2004	DI	NONRES		Installation record	Y	2004	Visual insp during install or repair	Diameter > 2 inches	Y	Visual insp during install or repair	
BADGER CUSTOM PALLET LLC	460 QUALITY CT	N	DI	N	6"	2004	DI	NONRES		Installation record	Y	2004	Visual insp during install or repair	Diameter > 2 inches	Y	Visual insp during install or repair	
CALAMARI TRUST	112 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
RABL, KAYLEN	120 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
ROBBINS, KYLE	129 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FICHTINGER, PAUL	133 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BERNDT, SEAN	134 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BUCHDA, MADELYN	138 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HANOUSEK, MICHAEL	142 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
PETRIE, TIMOTHY	143 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
ABEGGLEN, BRIAN	148 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
LEPKE, KATILYN	149 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MUHLNBECK, NICOLE	153 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DEGROOT, ROBERT & MARK	156 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GEHRKE, PHIL	167 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MCDONALD, RUTH	203 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
JAYNES, TIM	206 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
LANGTON, WILBERT	207 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
RENTMEISTER, TIMOTHY	211 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HUGGETT, TODD	216 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DYKSTRA, JOYCE	217 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
ZINDA, DALE	224 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
EWING, BANKRUPTCY	230 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
OELKE, GARY	231 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HUGHES, ROBERT	235 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MILLIOUS, MURIEL	236 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BROCK, HUNTER	238 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
SWISSDORF, JOEL & KIM	243 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
LYNN PROPERTIES LLC	244 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
LOHAUS, ANGELA	249 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VANDERWERFF, JOHN	252 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FLEISCHER, CHRISTY	302 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
RIVERS, TIM & ERICA	305 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MAENNER, CHARLES & ANNA	308 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GILLET, KENNETH	314 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HILLIARD, AMY	317 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HAZARD, BENJAMIN & PAULA	320 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HUBER, TIM	326 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BAASKE, TERRY	329 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VONHELLFIRE, RUTH	335 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
ROBBINS, JUDY	338 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BEATTIE, SHEILA	341 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DYKSTRA, JESSICA	346 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
NEUMAN, JOSEPH	403 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
KRUSEL, BARBARA	406 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
MARKART, DAWN	412 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BABILIUS, THADDEUS & EMILY	415 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WATTERS, JASON	418 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
RAMSEY, BEN	423 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FLETCHER, RUSS	424 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
REICHHOFF, LAURA	431 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
PRESTON, DALTON & STEPHANIE	432 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HEBERT, FRED	435 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
PIERCE, SHAWN	437 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GLACE, MICHAEL & AMY	440 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FRANK, BRIAN	505 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
OLSON, JON	510 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
BURBACH, STEVE	512 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
PAULMIER, JOSEPH	513 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HALL, NANCY	514 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FRANK, RANDY	519 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FRANK ENTERPRISES	525 S MAIN ST	N	C	N	1"	2003	C	NONRES		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2021	Cross-connection survey
FRANK, RANDY	525 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
JEROME, KAIDEN	526 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
GRUENEBERG, FRED & LORI	533 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
CJ'S BAR & RESTAURANT	538 S MAIN ST	N	C	N		2003	C	NONRES		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
KLUG, SARA	539 S MAIN ST	N	C	N		2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WINDFALL PROPERTY GROUP LLC	543 S MAIN ST	N	C	N			C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WINDFALL PROPERTY GROUP LLC	543 S MAIN ST	N	C	N			C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
WINDFALL PROPERTY GROUP LLC	543 S MAIN ST	N	C	N			C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
DEFEVER, RYAN	613 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
EISNER, KENT	615 S MAIN ST	N	C	N	1"	2003	C	MF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
TRAMBURG MOTORS	620 S MAIN ST	N	C	N	1"	2003	C	NONRES		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2023	Cross-connection survey
SLOTTEN, JEFF	625 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
HERWIG, DENNIS	628 S MAIN ST	N	C	N	1"	2003	C	SF		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
VILLAGE OF FALL RIVER	641 S MAIN ST	N	C	N	1"	2003	C	NONRES		SL repair/replace record	Y	2003	Visual insp during install or repair	Field inspection only	Y	2003	Visual insp during install or repair
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y	2021	Cross-connection survey
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
FALL RIVER FOUNDRY	670 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
EK MACHINE	671 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y		Visual insp during install or repair	Field inspection only	Y		
EK MACHINE	671 S MAIN ST	N	DI	N			C	NONRES		Installation record	Y						

ADLER, LISA	117 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, DIANNA	118 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
LUETH, APRIL	123 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DERR, JORDAN	124 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DONNER, SIGRUN	128 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
SEIDEMAN, CHELSIE	131 SOUTH ST	N	C	N	1"	2017	C	MF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
ROGNEY, THERESA	133 SOUTH ST	N	C	N	1"	2017	C	MF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
OPPOR, LYNN	134 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
OELKE, BRAD	135 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
ENGELHARDT, DAVE	138 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
FRANK, BRIAN	139 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
FROELKE, LELAND & NICOLE	145 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
FR UNITED METHODIST CHURCH	150 SOUTH ST	N	C	N	1"	2017	C	NONRES	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DOWDELL, MICHAEL	210 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
KOOPMAN, KIM	306 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
ROSS, CATHERINE	307 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
WEISENSEL, JAPETH & AMANDA	310 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
JAYNES, BILL	313 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
TRAMBURG, BRYAN	316 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
SCHULTZ, DAVID & ANGELICA	321 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, RICHARD	322 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, KERIA	325 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
SCHULTZ, CRAIG	333 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
LEISMANN, EUGENE	334 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
WEISENSEL, JULIUS & MEGAN	341 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
NELSON, DANIELLE	346 SOUTH ST	N	C	N	1"	2017	C	SF	SL repair/replace record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
BERNDT, RUSSELL	357 SOUTH ST	N	C	N	1"	2017	C	SF	Visual insp during install or repair	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
DYKSTRA, MARK	386 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during install or repair	Installation record	Y		
DYKSTRA, MIKE	394 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during install or repair	Installation record	Y		
DYKSTRA, RENEE	396 SOUTH ST	N	C	N	1"	2001	C	SF	Installation record	Y	2001	Visual insp during install or repair	Installation record	Y		
BROWN, JOHN & MADOLYN	398 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
GUMZ, CODY	400 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
KURLINSKI, JOANNE	411 SOUTH ST	N	C	N	1"	2017	C	SF	Installation record	Y	2017	Visual insp during install or repair	Field inspection only	Y	2017	Visual insp during install or repair
FALL RIVER COMMUNITY FIRE DIST	450-16 SOUTH ST	N	C	N	1"	2017	C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y	2023	Cross-connection survey
FALL RIVER COMMUNITY FIRE DIST	450-17 SOUTH ST	N	C	N	1"	2017	C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y	2023	Cross-connection survey
METALCRAFT OF MAYVILLE INC	200 STEEL RD	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
METALCRAFT OF MAYVILLE INC	200 STEEL RD	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
FALL RIVER POST OFFICE	203 STEEL RD	N	C	N	1"		C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
ESMILCO INC	209 STEEL RD	N	C	N	1"		C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
OELKE WAREHOUSE	642 STEEL RD	N	C	N	1"		C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
GOULD PLUMBING	680 STEEL RD	N	C	N	1"		C	NONRES	Installation record	Y		Visual insp during install or repair	Installation record	Y		
ORMOSEN, PAULA	698 STEEL RD	N	C	N	1"		C	SF	Installation record	Y		Visual insp during install or repair	Installation record	Y		
BORDE, CHRISTOPHER & KATHRY	100 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
YUDS, ERIC & ANGELA	102 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
SMITH, BENJAMIN	105 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
TRAMBURG, WYATT & CARISSA	112 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
SCHULZE, GERALD	115 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
FARR, THOMAS & PEGGY	120 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
FRIEDLAND, CLAYTON & JODI	123 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
GAYDOS, JOHN	128 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
WAGNER, MALORY	131 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
WEINBERGER, DAN	136 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
KUEHL, TERRY	139 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
MICKELSON, CRAIG	144 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
DAUMAN, KELSEY	147 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
YUDS, KELLY	152 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
VOIGHT, JOHN & SARAH	155 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
WALTER, KEVIN	160 SUNRISE LN	N	C	N	1"	2022	C	SF	SL repair/replace record	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
BROWN, DEREK	163 SUNRISE LN	N	C	N	1"	2022	C	SF	Visual insp during install or repair	Y	2022	Visual insp during install or repair	Field inspection only	Y	2022	Visual insp during install or repair
MACHKOVITZ, RHEA	168 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
MOBRY, RYAN & OLIVIA	171 SUNRISE LN	N	C	N	1"	1996	C	SF	Visual insp during install or repair	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
STORMER, TIMOTHY & NICOLE	176 SUNRISE LN	N	C	N	1"	1996	C	SF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
FRISH, SUE	179 SUNRISE LN	N	C	N	1"	1996	C	SF	Visual insp during install or repair	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
PRIVETT, KELLY	201 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
EDWARDS, JONATHON & AUBREY	202 SUNRISE LN	N	C	N	1"	1996	C	SF	Visual insp during install or repair	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
MAZZUCA, JOHN & KRYSTAL	203 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
JOHNSON, ROBYN	204 SUNRISE LN	N	C	N	1"	1996	C	SF	Visual insp during install or repair	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
MILLER, MATTHEW	205 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
DUNBAR, AMANDA	207 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
HUEBNER, ANDY	209 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
MITCHELL, SHEENA	211 SUNRISE LN	N	C	N	1"	1996	C	MF	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
GRUCHOW, JUSTIN	213 SUNRISE LN	N	C	N			C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
BENNETT, CHRISTINE	215 SUNRISE LN	N	C	N			C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
BUBOLZ, SHANNON	217 SUNRISE LN	N	C	N			C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
JOHNSON, LINDA	219 SUNRISE LN	N	C	N			C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
LANDMARK INVESTMENTS	201-211 SUNRISE LN	N	C	N			C	MF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
SCHUMANN PRINTERS	200 SWARTHOUT RD	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
SCHUMANN PRINTERS	200 SWARTHOUT RD	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
VITA BUILDERS LLC	235 SWARTHOUT RD	N	C	N	1"	2000	C	NONRES	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
SHEETMETAL SPECIALTIES IN	250 SWARTHOUT RD	N	DI	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
DAUMAN ELECTRIC	295 SWARTHOUT RD	N	C	N	1"	2000	C	NONRES	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
WB EQUIPMENT SALES INC	300 SWARTHOUT RD	N	C	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
WB EQUIP BLDG #2	300B SWARTHOUT RD	N	C	N	1"	2019	C	NONRES	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
SPURBECK, RON	105 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
LECLAIR, RYAN & LISA	109 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
PEDERSON, CHAD	113 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
HUMPHREY, JASON	117 TRANQUIL CT	N	C	N	1"	2007	C	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
UNITED COOP	114 VITA PLUS DR	N	C	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
IDO FEED SUPPLY	638 VITA PLUS DR	N	C	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair
VITA PLUS GRAIN	640 VITA PLUS DR	N	C	N			C	NONRES	Installation record	Y		Visual insp during install or repair	Field inspection only	Y		Visual insp during install or repair